

STANDARD INSTRUMENT DEPARTURE (SID) RWY 10

Designator	Route	After Take-off		Remarks
		Climb to ALT/FL	Contact	
AMSEL6E	Turn right to intercept and proceed on RDL 178 VFA DVOR/DME to AMSEL	FL060	FARO APPROACH 119.405 MHZ	
BAROK6E	Turn right to track 277° to intercept and proceed on RDL 241 VFA DVOR/DME to BAROK			
NARTA6E	Turn right to track 277° to intercept and proceed on RDL 259 VFA DVOR/DME to NARTA			
ODEMI6E	Turn right to VFA DVOR/DME; proceed on RDL 329 VFA DVOR/DME to ODEMI			Cross VFA DVOR/DME at 2500FT QNH or above.
ORTOP6E	Turn right to intercept and proceed on RDL 157 VFA DVOR/DME to ORTOP			
XAPAS8E	Climb on Runway heading. When passing 3000FT QNH but not before 4NM VFA DVOR/DME, turn left track 326 to intercept and proceed on RDL005 VFA DVOR/DME to XAPAS.			Only to be assigned by ATC.
XAPAS6L	Turn left to intercept and proceed on RDL005 VFA DVOR/DME to XAPAS			Only to be assigned by ATC. For light Aircraft only.