



MAG VAR changed. New RWY designator.

Missed Approach Procedure RCF Coding Table  
Lisboa RNP RWY 02

Path Terminator	Waypoint				Course/Track MAG (True)	Dist NM	Turn Direction	Altitude	Speed	RNP Value NM	Navigation Specification	Remarks
	Identifier	Type	Flyover	Coordinates								
IF	RW02	MAPt (LNAV only)	Y	384559.15N 0090838.04W			-			1.0	RNP APCH	-
TF	PT544	-	N	385036.16N 0090609.86W	025 (022.7)	5.00	-		-	1.0	RNP APCH	-
TF	PT801	-	Y	385305.88N 0090449.36W	025 (022.8)	2.7	R		-	1.0	RNP APCH	-
TF	PT802	-	N	385204.54N 0083544.66W	094 (092.4)	22.73	R	@FL070	-	1.0	RNP APCH	-
TF	PT803	-	N	383405.42N 0083802.02W	188 (185.7)	18.06	R	@FL070		1.0	RNP APCH	-
TF	ADSAD	-	Y	382840.65N 0085852.27W	254 (251.8)	17.22	R	@FL070	-	1.0	RNP APCH	-
HM	ADSAD	-	N	382840.65N 0085852.27W	343 (340.9)	5.00	R	@FL070	-	1.0	RNP APCH	
TF	PT421	IF	N	382719.25N 0091835.19W	267 (265.1)	15.55	R	+4000 FT	-	1.0	RNP APCH	-
TF	PT422	IAF	N	383100.92N 0091637.34W	025 (022.7)	4.00	R	+4000 FT	-	1.0	RNP APCH	-
TF	PESEX	FAP/FAF	-	383532.42N 0091412.69W	025 (022.7)	4.90	R	@4000 FT	-	1.0	RNP APCH	-